

## Vented Major Repair Garage - 2008 NEC 511.3

Ceiling - unclassified where ventilation is within 18" of the highest point of the ceiling.

In a vented pit of a major repair facility the pit is Class 1 Div 2. The floor area of a major repair facility is unclassified. The ceiling area of a vented major repair facility is unclassified. Refer to NEC 511.3 for venting requirements.

Floor Level - unclassified where ventilation is taken within 12" of the floor.

Vented  
Pit  
Class 1  
Div 2